



Photo 1 OCT 2 1978
Coite-Hubbard House
Middletown, CT.

D. Ransom Photo 3/78
Negative: Connecticut
Historical Commission
View Northwest

DEC 20 1978



Photo 2 **OCT 2 1978**

Coite-Hubbard House
Middletown, CT

D. Ransom Photo 3/78

Negative: Connecticut
Historical Commission
View northwest

DEC 20 1978



Photo 3 **OCT 2 1978**

Coite-Hubbard House
Middletown, CT

D. Ransom Photo 5/78
Negative: Connecticut
Historical Commission
Doorway, view west

DEC 20 1978



Photo 4 **OCT 2 1978**

Coite-Hubbard House
Middletown, CT

D. Ransom Photo 5/78

Negative: Connecticut
Historical Commission
First floor front window,
view west

DEC 2 0 1978



OCT 2 1978

Photo 5

Coite-Hubbard House
Middletown, CT

D. Ransom Photo, 3/78
Negative: Connecticut
Historical Commission
North veranda, view
southwest

DEC 20 1978



Photo 6 **OCT 2 1978**
Coite-Hubbard House
Middletown, CT

D. Ransom Photo, 5/78
Negative: Connecticut
Historical Commission
Roofline, view northwest

DEC 20 1978



Photo 7 OCT 2 1978

Coite-Hubbard House

Middletown, CT

D. Ransom Photo, 3/78

Negative; Connecticut

Historical Commission

Fence, view southwest

DEC 20 1978



Photo 8 OCT 2 1978
Coite-Hubbard House
Middletown, CT
D. Ransom Photo, 5/78
Negative: Connecticut
Historical Commission
Stairway, view southwest

DEC 20 1978



Photo 9 OCT 2 1978
Coite-Hubbard House
Middletpwn, CT
D. Ransom Photo, 5/78
• Negative: Connecticut
Historical Commission
Drawing room fireplace,
view east

DEC 20 1978



Photo 10 OCT 2 1978

Coite-Hubbard House
Middletown, CT

D. Ransom Photo, 3/78
Negative: Connecticut
Historical Commission
Drawing room chandelier,
view northwest

DEC 20 1978




Photo 11 OCT 2 1978

Coite-Hubbard House
Middletown, CT

D. Ransom Photo, 3/78
Negative: Connecticut
Historical Commission
Cellar, view west

DEC 2 0 1978



Photo 12

Coite-Hubbard House

Middletown, CT

D. Ransom Photo, 12/78

Negative: Connecticut

Historical Commission

Rear addition, view

northeast MAR 1 1979